

FIG. 1

$W_k^N$	N=4	N=8	N=16	N=32	N=64	N=128
k	0	0	0	0	0	0
						64
					32	32
						96
				16	16	16
						80
					48	48
						112
				8	8	8
						72
					40	40
						104
			8	24	24	24
						88
					56	56
						120
			4	4	4	4
						68
					36	36
						100
				20	20	20
						84
					52	52
						116
				12	12	12
						76
					44	44
						108
			12	28	28	28
						92
					60	60
						124

$W_k^N$	N=4	N=8	N=16	N=32	N=64	N=128
k	2	2	2	2	2	2
						66
					34	34
						98
				18	18	18
						82
					50	50
						114
			10	10	10	10
						74
					42	42
						106
				26	26	26
						90
					58	58
						122
		6	6	6	6	6
						70
					38	38
						102
			22	22	22	22
						86
					54	54
						118
		14	14	14	14	14
						78
					46	46
						110
			30	30	30	30
						94
					62	62
						126

$W_k^N$	N=4	N=8	N=16	N=32	N=64	N=128
k	1	1	1	1	1	1
						65
					33	33
						97
				17	17	17
						81
					49	49
						113
			9	9	9	9
						73
					41	41
						105
				25	25	25
						89
					57	57
						121
		5	5	5	5	5
						69
					37	37
						101
			21	21	21	21
						85
					53	53
						117
		13	13	13	13	13
						77
					45	45
						109
			29	29	29	29
						93
					61	61
						125

$W_k^N$	N=4	N=8	N=16	N=32	N=64	N=128
k	3	3	3	3	3	3
						67
					35	35
						99
				19	19	19
						83
					51	51
						115
		11	11	11	11	11
						75
					43	43
						107
			27	27	27	27
						91
					59	59
						123
		7	7	7	7	7
						71
					39	39
						103
			23	23	23	23
						87
					55	55
						119
		15	15	15	15	15
						79
					47	47
						111
			31	31	31	31
						95
					63	63
						127

FIG. 2





FIG. 3



**FIG. 4**